

CONCRETE MOISTURE ENCOUNTER



QUICK START GUIDE

OPERATION

- Press U to switch ON/OFF.
- Press the Concrete Moisture Encounter fully against the surface of the concrete slab or screed. (Surface should be smooth and free of coatings/contaminants).
- Readings are instant and displayed on analog dial.



- Hold/freeze: Press ① once. In HOLD mode the Hold LED will flash continuously. Press ② again to release hold. (If powered down while on Hold, the Concrete Moisture Encounter will retain information until powered up and hold is pressed again to release)
- Automatic power timeout (5 mins) conserves battery life.

SCALES

- Top Scale Red for use with Concrete Slabs & Sand/Cement screeds.
 - Equivalent reading to Moisture Content (MC%) or moisture by mass/weight as per the oven dry/gravimetric method.



- Middle Scale Blue for use with Anhydrite, Hemihydrate or Calcium Sulphate Screeds.
 - Equivalent reading to Carbide Method (CM) test for Anhydrite.
- Bottom Scale Yellow for use with Concrete slabs or Sand/Cement screeds.
 - Equivalent reading to Carbide Method (CM) test for Concrete.

BLUETOOTH

Press
 To switch Bluetooth ON/OFF. Readings will be sent to the Tramex App on your mobile device.

CALIBRATION & WARRANTY

- Obtain Warranty online: tramexmeters.com/register
- Annual calibrations are recommended as best practice to ensure continued accuracy and reliability. Calibration Check Plates can be purchased for more regular checks.

TROUBLESHOOTING

- All LEDs flashing when unit is powered up.
 - Batteries are low and will soon need to be replaced.
- Single LED flashing and meter frozen.
 - Concrete Moisture Encounter is in HOLD mode.
 - Press HOLD button to release.

USER GUIDE ONLINE

Please use the following link or QR code to access the complete User Guide online: http://l.ead.me/bb3SEA



Free App Available for Mobile and Tablet:





LI-CME5AOSG

